Doug Rauh's comments as of 2019 09 05.


By having the trash bin inside the secure parking area the gate has to be opened for every pickup. This would increase the Life Cycle Cost of this police station which has at least a fifty year life.

A Sally Port was one of the most important upgrades asked for yet it is not marked on the diagram. What is marked is a "roof canopy" by the "suspect entry".

Yet the "Covered Impound Parking" has "overhead Door each bay" with "fenced wall".

This is backwards, the "Sally Port" should have the overhead doors and fenced wall.

I do not want to see concertina wire on the Security Fence.



Note
plan set including site plan, elevations,

conceptual and drainage plans

Created Attachments

7/30/2019 51524 PRE Plan Set 1.pdf

