

Subject: Photos from Easement property relating to  
Milligan-E Preliminary PLN50803 SPT – 10543 Falk RD NE, TA#14250210572009

These photos are meant to highlight the drainage issue along the easement on the property in question. They were taken for personal family use but can hopefully provide information on the issue. All photos were taken by Leanne Wetzel (10521 Falk Rd).



Photo 1: Standing on easement looking north on Falk. Water often pools in front of mailboxes. Photo taken January 25, 2016





Photo 2: Standing at the end of the easement facing southwest to the property 10525 Falk. Photo taken October 15, 2016





Photo 3: Pooling water on the property just north of easement. This pooling is bordering the easement. Photo taken November 25, 2016





Photo 4: Pooling water on the property just north of the easement. Taken from the easement facing northwest. Photo also from November 25, 2016





Photo 5: Pooling water and potholes on property just north of the easement. Photo also from November 25, 2016. While we don't have photos of it, the pooling water rises up and washes out parts of easement during decent rains. (for reference: child is 31 inches tall)





Photo 6: Photo of easement facing property 10525 Falk after neighbors on easement repaired potholes in January 2017. Photo from April 16, 2017





Photo 7: Photos on the end of the easement facing property 10525 Falk. Photo taken May 3, 2017.





[illegible]



